

July 6, 2023

An inspection of the billboard located at 16912 ½ IH 35 has been completed. The physical visual inspection revealed no structural defects and is in sound order. See included inspection.

Michael Scutt

MS 7/6/23

Billboard Operations

7020 Highway 290 East

Austin, Texas 78623

Cell: (512)-718-8589

mscutt@austincrane.com

**Austin Crane Service
Billboard Inspection
Field Report**

Inspector (all)

print MICHAEL SUTT

Sign



Date 7/5/23

Panel Numbers

1609 / 16101

Board type

STATIC - DIGITAL

Location Discription

35w/s .25mIS/0.1325

NOTES

Line of Sight RH/F

Good Needs Atten. _____

Line of Sight LH/F

Good Needs Atten. _____

Base Footing

Good Needs Atten. _____

Column Base

Good Needs Atten. _____

Column Sections

Good Needs Atten. _____

Attached ladder

Good Needs Atten. _____

Vertical Safety

Cable

Good Needs Atten. _____

Head Plate

Good Needs Atten. _____

Head Bolts

Good Needs Atten. _____

ALLTIGHT.

Catwalk Safety

Cables

Good Needs Atten. _____

Catwalks

Good Needs Atten. _____

**Upright connections
to Torsion Tube**

Good Needs Atten. _____

**Cross bracing
connection to
uprights**

Good Needs Atten. _____

Stringer connection

Good Needs Atten. _____

Face connections

Good Needs Atten. _____