

Certificate of Appropriateness ApplicationHistoric Preservation Commission

Submit this form and all necessary attachments (see checklist) at least 14 days before the Historic Preservation Commission meeting to the Planning & Development Services Department, 301 W. Bagdad Avenue, Suite 210, Round Rock, Texas 78664; ph. 512-218-5428.

Applicant contact information	
Name: Erik Hall	
Address: 110 S Lampasas St. Suite 2, Round Rock TX 78664	
	Email: erik@hallroofing.com
Role: Owner Architect/contractor Other: Contractor and Tenant	
Developer contact information	
Name: Hall Roofing and Construction	
Phone: 512-818-2954 Fax:	Email: erik@hallroofing.com
Property Address: 117B E Main Street, Round Rock TX 78664	
1. In the space below, briefly describe the work proposed (use separate page(s) if necessary).	
2. Please refer to the attachment checklist for additional materials necessary to evaluate the proposed work.	
Description of proposed work:	
 Refinish rear door and install new hardware. Install 2 windows on the East side of the building. 7.5 wide, 4 feet tall. Replace rotted window trim molding with the same profile. Paint rear window trim. Remove overgrown vegetation. Repair masonry as needed with salvaged material from window installation. 	
(a) Repair masonry as needed with salvaged material north window installation.	
1 bel	04/40/0040
Signature	04/12/2016 Date

..9 .92

Main Level

Z (

Proposed Windows

Page: 10



110 S Lampasas St. Suite 2 Round Rock TX, 78664 (512) 212-4333 (877) 620-ROOF

1 3-IMG_4385

Date Taken: 4/4/2016

Elevation



2 4-IMG_4387 Date Taken: 4/4/2016

Requesting to repair handrail and paint black.





110 S Lampasas St. Suite 2 Round Rock TX, 78664 (512) 212-4333 (877) 620-ROOF

3 5-IMG_4389 Date Taken: 4/4/2016

Requesting to remove vegetation.



4 7-IMG_4391 Date Taken: 4/4/2016

Requesting to remove vegetation.





110 S Lampasas St. Suite 2 Round Rock TX, 78664 (512) 212-4333 (877) 620-ROOF

5 8-IMG_4392 Date Taken: 4/4/2016

Replace rotted trim with the same profile. Paint trim.



6 9-IMG_4393 Date Taken: 4/4/2016

Paint trim to be a similar color as original. (Colors are in the proposal packet)





110 S Lampasas St. Suite 2 Round Rock TX, 78664 (512) 212-4333 (877) 620-ROOF

7 10-IMG_4394 Date Taken: 4/4/2016

Replace hardware, repair and refinish door.



8 25-IMG_4507 Date Taken: 4/7/2016

Previous hardware





110 S Lampasas St. Suite 2 Round Rock TX, 78664 (512) 212-4333 (877) 620-ROOF

9 11-IMG_4395 Date Taken: 4/4/2016

Repair and refinish door. A darker color will be necessary.



10 19-IMG_4408 Date Taken: 4/5/2016





110 S Lampasas St. Suite 2 Round Rock TX, 78664 (512) 212-4333 (877) 620-ROOF

11 22-IMG_4504 Date Taken: 4/7/2016

Remove electrical outlet and conduit to install windows.



12 23-IMG_4505 Date Taken: 4/7/2016

Elevation of window proposal.





110 S Lampasas St. Suite 2 Round Rock TX, 78664 (512) 212-4333 (877) 620-ROOF

13 28-IMG_4595

Date Taken: 4/10/2016


East Elevation where windows are proposed.



14 30-IMG_4597

Date Taken: 4/10/2016

Overview






110 S Lampasas St. Suite 2 Round Rock TX, 78664 (512) 212-4333 (877) 620-ROOF

15 32-IMG_4601

Date Taken: 4/10/2016

Chaulk indication the location of the proposed windows. Fan must be removed.



16 34-IMG_4603

Date Taken: 4/10/2016

Overview





110 S Lampasas St. Suite 2 Round Rock TX, 78664 (512) 212-4333 (877) 620-ROOF

17 42-Window Example

Example of proposed window



2016-04-12-1810

